L Number	Hits	Search Text	DB	Time stamp
1	32182	((stress strain force load) near2 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5)).clm.	USPAT; EPO; JPO	2004/10/09 12:10
2	152	(((stress strain force load) near2 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5)).clm.) and (suspend\$5 near3 load).clm.	USPAT; EPO; JPO	2004/10/09 12:12
3	53	((((stress strain force load) near2 (test\$5 detect\$5 sens\$5 estimat\$5 evalut\$5 determin\$5 measur\$5 transducer cell meter gauge monitor\$5)).clm.) and (suspend\$5 near3 load).clm.) and (upper lower).clm.	USPAT; EPO; JPO	2004/10/09 12:10
4	45	(suspend\$5 near3 load near3 cell).clm.	USPAT; EPO; JPO	2004/10/09 12:13